

Oregon DEQ Facility Profiler 2.0



[Help] [Close Window]



Facility Summary Report

[Facility Profiler](#) [Print Report](#)

Maps



Facility / Site Information for Location 470

Facility/Site Name: KNAPPTON CORPORATION
Address: 9030 NW SAINT HELENS RD
City State Zip: PORTLAND OR 97231-1127

Latitude: 45° 35' 15"
Longitude: -122° 46' 16"
Location Accuracy: HIGH
Last Updated: 3/23/2004

Aliases

Brix Maritime	ECSI	FOSS MARITIME	UST
Foss Maritime Co	HW	Foss Maritime/Brix Maritime	ECSI
Knappton Corp.	ECSI	KNAPPTON CORPORATION/BRIX MARITIME	LUST
Portland Harbor Sediment Study	ECSI		

Geographic Features

Township: T1N-R1W-S11 **Congress Dist:** 3 **Forest Type:**
County: MULTNOMAH **OR Senate Dist:** 17 **Vegetation:** Douglas fir-western hemlock-grand fir forest
Watershed: LOWER WILLAMETTE **OR House Dist:** 33 **Agricultural Land:** N/A

Oregon DEQ Program Information

Underground Storage Tanks (UST)

UST Facility ID	Permit Number	Installed	Content	Gallons	Status	Reg Cert NO
7374	AEFG	05/06/1979	DIESEL	20000	ACTIVE	26-7374-1998-OPER
7374	AEFH	05/06/1979	DIESEL	20000	ACTIVE	26-7374-1998-OPER
7374	AEGK	05/06/1979	OTHER	6000	ACTIVE	26-7374-1998-OPER

Environmental Cleanup (ECSI)

Operation ID	Start Date	Issue Date	Expiration Date	Permit Type	Permit SubType	Status	Detail Information ¹	EPA Number
2364	06/08/1999			Contaminated Site		Listed on CRL or Inventory	ECSI Site Report	

SIC CODE	SIC Description	PRIMARY
3462	IRON AND STEEL FORGINGS	Y

USEPA SF



1386131

4400	WATER TRANSPORTATION	Y
------	----------------------	---

Hazardous Waste (HWMS)

Identifier	Start Date	Effective Date	Review Date	NFA Date	Type	Sub Type	Detail Information ¹	EPA Number
3630	04/01/1992	12/31/2003			Generator	CEG	HW Site Report	ORD103014866

SIC CODE	SIC Description	PRIMARY
4492	TOWING AND TUGBOAT SERVICE	N

Leaking Underground Storage Tanks (LUST)

Log Number	Received	Cleanup Initiated	Cleanup Complete	Type	Heating Oil Tank	UST Facility ID	Status	Detail Information ¹
26-93-0009	01/13/1993	01/13/1993	05/16/2002	REGULATED		7374	CLEANUP_COMPLETED	LUST Site Report

¹ Linked reports may be unavailable from 9:00pm to 7:00am PST due to system maintenance.

² DEQ does not maintain air discharge permit information for Lane County.

More Information on this location

[Oregon DEQ Neighborhood Info \(by region/county\)](#)

[See wells in the same Township Range Section from the Oregon Water Resources Department Well logs Application](#)

[See county's scanned assessor maps through ORMAP](#)

[\[DEQ's Privacy Notice\]](#) [\[Contact DEQ\]](#) [\[Application Feedback\]](#)

Disclaimer: *This product is for informational purposes, and may not be suitable for legal, engineering or surveying purposes. This information or data is provided with the understanding that conclusions drawn from such information are the responsibility of the user.*